
PORTUGAL

PHONE: +351.21.8553506
FAX: +351.21.8553399
E-Mail: desica@nav.pt
AFTN: LPPPYOYC



DSEQ-DIREÇÃO DE SEGURANÇA, ESTRATEGIA E
QUALIDADE
AERONAUTICAL INFORMATION SERVICE
APARTADO 8223
1803-001 LISBOA CODEX

SUP
MVFR
018 / 2018
FEB 02

LPIN AD - RWY PAVEMENT IRREGULARITIES **LPIN AD- RWY IRREGULARIDADES NO PISO**

ENGLISH VERSION

LPIN AD - RWY 17/35 with irregularities due to lack of small pieces of asphalt and presence of small rocks.
All aircraft movements must be done in low speed.
All non-resident operators must request prior permission to AD Director with at least 48 hours in advance.

Validity: from 02-FEB-2018 and end date UFN.

This Supplement replaces SUP 040/2017

VERSÃO PORTUGUESA

LPIN AD - Pista 17/35 apresenta irregularidades no piso devido a falhas de asfalto e presença de pequenas pedras soltas.
A rolagem para estacionamento ou para a pista deverá ser feita em marcha lenta.
Os operadores não residentes deverão solicitar autorização prévia ao Director do Aeródromo com pelo menos 48 horas de antecedência.

Validade: início a 02-FEV-2018 e final de validade UFN.

Este Suplemento substitui os SUP 040/2017

=END OF SUPPLEMENT=
=FIM DO SUPLEMENTO=

THIS PAGE INTENTIONALLY LEFT BLANK