

---

# PORTUGAL

---

PHONE: +351.21.8553506  
FAX: +351.21.8553399  
E-Mail: desica@nav.pt  
AFTN: LPPPYOYC



DSEQ-DIREÇÃO DE SEGURANÇA ESTRATÉGIA E QUALIDADE  
AERONAUTICAL INFORMATION SERVICE  
APARTADO 8223  
1803-001 LISBOA CODEX

**SUP**  
**MVFR**  
**010 / 2013**  
**JUL 25**

---

**LPIN - TWY and STRIP RWY 17/35 with degraded pavement**  
**LPIN - TWY e STRIP RWY 17/35 com piso mau estado conservação**

## ENGLISH VERSION

- LPIN (Espinho) Taxiways with degraded pavement and without markings. Strip runway 17/35 with degraded pavement.

This supplement replaces NOTAM C0210/13 C0211/13

## VERSÃO PORTUGUESA

- LPIN (Espinho) Piso dos caminhos de circulação em mau estado de conservação e sem marcas de sinalização. Bermas da pista 17/35 em mau estado de conservação.

Este suplemento substitui os NOTAM D0390/13 D0391/13

=END OF SUPPLEMENT=  
=FIM DO SUPLEMENTO=

---

THIS PAGE INTENTIONALLY LEFT BLANK